

Succinct summary of representative risk management measures (RMMs) and operational conditions (OCs)

Legal name of applicant(s):	Derby Plating Services Ltd East Lancashire Platers Ltd Global Metal Finishing Ltd Hard Anodising Surface Treatments Ltd Nu-Pro Limited Russell Laboratories Ltd Twickenham Plating Ltd Walton Plating Ltd
Submitted by:	Surface Engineering Association Chromium Trioxide Authorisation Consortium
Date:	21 st March 2023
Substance:	Chromium Trioxide EC: 215-607-8 CAS: 1333-82-0
Use title:	Use of chromium trioxide for the surface treatment of engineering components, mainly for the aerospace and defence sector with the purpose of creating a coating to meet specific and critical performance characteristics.
Use number:	1

Exposure Scenario Use at an Industrial Site - Use of chromium trioxide for the surface treatment of engineering components, mainly for the aerospace and defence sector with the purpose of creating a coating to meet specific and critical performance characteristics.

ECS and WCS	Task (ERC/spERC or PROC)	Annual amount per site (tonnes /year)	Technical RMMs, including: *Containment, *Ventilation (general, LEV...) *customized technical installation, etc	Organisational RMMs, including: *Duration and Frequency of exposure *OSH management system *Supervision *Monitoring arrangements *Training, etc	PPE (characteristics)	Other conditions	Effectiveness of waste water and waste air treatment (for ERC)	Release factors: water, air and soil (for ERC)	Detailed info. in CSR (section)
ECS 1	Use in chromium Electroplating	500 – 750kgs in total for all sites					No direct emissions to the environment	No emissions to soil. No direct emissions to air outside of the site No direct emissions to water	
WCS 1	Receipt, transfer and storage of chromium trioxide PROC8a	See above	General ventilation	All persons with access to the storage areas have been informed of the risks of working with chromium trioxide, the safe way of handling chromium trioxide and use of PPE and other control equipment.	Safety shoes, suitable gloves and eye protection as required	None	Not applicable	Chromium trioxide is in sealed containers – no exposure	9.2.1.1
WCS 2	Loading / unloading of jigs PROC 0	See above	General ventilation	Exposure to chromium trioxide is not possible from loading components onto jigs. Processed components may	Suitable gloves	Ensure adequate rinsing to remove process solutions	Not applicable	No exposure	9.2.2.1

				contain minute traces of chromium trioxide if rinsing processes are not completed correctly					
WCS 3	Operation of surface treatment line PROC 13	See above	Mist suppressant or surface tension modifiers are used to control any potential emissions of chromium trioxide from anodising processes. Other processes do not give rise to emissions of chromium trioxide.	Mist test measurements taken at least every 2 weeks, to ensure compliance with UK legislation. Individual air monitoring. Biological Monitoring	Suitable gloves, eye protection, clothing and footwear	None		In line with current UK ALARP principles	9.2.3.1
WCS 4	Sampling the surface treatment solution PROC19	See above	Mist suppressant or surface tension modifiers are used to control any potential emissions of chromium trioxide.	All persons undertaking sampling activities have been instructed about the risks of working with chromium trioxide, the safe way of handling chromium trioxide and the use of PPE and other control equipment.	Suitable gloves, eye protection, clothing, footwear and respiratory protection where required	None			9.2.4.1
WCS 5	Making additions of chromium trioxide PROC 0	See above	Mist suppressant or surface tension modifiers are used to control any potential emissions of chromium trioxide from anodising processes. Chromium trioxide is in solid form	All persons undertaking making additions activities have been instructed about the risks of working with chromium trioxide, the safe way of handling chromium trioxide and the use of PPE and other control equipment.	Suitable gloves, eye protection, clothing, footwear and respiratory protection where required masks	None			9.2.5.1

WCS 6	Maintenance PROC 28	See above		All persons undertaking maintenance activities have been instructed about the risks of working with chromium trioxide, the safe way of handling chromium trioxide and the use of PPE and other control equipment.	Suitable gloves, eye protection, clothing, footwear and respiratory protection where required	None			9.2.6.1
WCS 7	Wastewater & effluent treatment PROC 0	See above	All solid and any liquid waste is collected and either forwarded to an external waste management company, or is treated on site by reducing the hexavalent chromium to trivalent chromium. The treated waste is either recycled or forwarded to an external waste management company (licenced contractor) for disposal as hazardous waste	Suitable training Use of licenced waste contractors Operating with the issued consent to discharge limits	Suitable gloves, eye protection, clothing and footwear	None	To comply with consent to discharge conditions where appropriate		9.2.7.1

Abbreviations: WCS=Worker contributing scenario, ECS=Environmental Contributing Scenario,* ERC=Environmental Release Category (or spERC if available) , PROC= Process category, LEV=Local Exhaust Ventilation, PPE=Personal Protective Equipment